

2016.6.13

Overview:

1. All-in-One firmware version updated to v1.9.60
2. DJI GO app iOS version updated to v2.8.3
3. DJI GO app Android version updated to v2.8.1

What's New:

1. Updated the Flight Restriction Zone database.
2. Fixed the Intelligent Flight Battery to prevent automatic restarting in cold environments.

Notes:

- Users are advised to update all Intelligent Flight Batteries with this All-in-One firmware.

2016.4.7

Overview :

4. All-in-One firmware version updated to : v1.8.80
5. DJI GO app Android version updated to: v2.7.2

What's New :

3. Improved aircraft stability through optimized flight controller logic.
4. Optimized gimbal parameters.
5. Fixed clip preview error in 2.7K resolution mode.
6. Improved encryption to enhance security during transmission.

Notes :

- Both the aircraft and the remote controller must be upgraded or else they will not link.

2016.3.15

Overview :

1. All-in-One firmware version updated to : v1.7.0060
2. DJI GO app iOS version updated to: v2.7.1
3. DJI GO app Android version updated to: v2.7.0

What 's New :

1. Improved compass accuracy.
2. Fixed issue of image being corrupted in rare occasion.

Notes :

- The firmware can be downgraded to v1.6.0040.

2015.12.22

Overview :

1. All-in-One firmware version updated to : v1.6.0040
2. DJI GO app iOS version updated to: v2.4.2
3. DJI GO app Android version updated to: v2.4.3

What 's New :

1. Improved battery reliability when using the aircraft in cold environments.
2. Optimized battery management.

Notes :

1. Users are advised to update all the Intelligent Flight Batteries with this All-in-One firmware.
2. The firmware can be downgraded to v1.5.30.

2015.9.3

Overview :

1. All-in-one firmware version updated to : v1.4.0010
2. DJI GO app iOS version updated to: v2.2.0
3. DJI GO app Android version updated to: v2.1.0

What 's New :

1. Added Intelligent Navigation Modes including Point of Interest, Follow Me and Waypoint.
2. The Phantom 3 Advanced now supports 2.7K (2704x1520p30) video recording.
3. The photo format now cannot be changed when the camera is in operation.

Bug Fixes :

1. Removed the vision position system altitude record from the video caption.

2015.8.4

Overview :

1. All-in-one firmware version updated to : v1.3.20
2. DJI GO app iOS version updated to: v2.0.0
3. DJI GO app Android version updated to: v2.0.0

What 's New :

1. Added HD Video Conversion option in the video editor when cutting footage to video.
2. Automatic photo syncing of the compressed file to your mobile device.
3. Added option to downgrade the aircraft firmware (remote controller version will be released soon).
4. Camera View now displays the DJI logo if a video output error is detected to avoid confusion with a blank screen.

Bug Fixes :

1. Fixed issue of the camera failing to save photos when shooting in burst mode.
2. Fixed issue of Camera View occasionally displaying a blank screen while recording video.

Notice :

- The firmware can be downgraded to v1.1.9 or later only.

2015.6.18

Overview :

1. All-in-One Firmware version updated to : v1.2.8

Major Updates :

1. Fixed issue of unwanted lines at the bottom of photos and videos when the image scale is set to 4:3.

Notice :

- Users may skip updating the remote controller if they have already updated the firmware to v1.2.7, as the latest firmware update does not affect the remote controller.

2015.6.15

Overview :

1. All-in-One Firmware version updated to : v1.2.7

Major Updates :

1. Anti-distortion feature added for images and non-4K videos.
2. Various bug fixes.

2015.5.22

Overview :

1. All-in-One Firmware version updated to : v1.1.9

Major Updates :

1. Fixed issue of some aircraft unable to determine their altitudes.
2. Fixed issue of the DJI Pilot app unable to obtain and display battery error history.
3. Fixed issue of the compass calibration progress not being displayed properly.

Notice :

- Users are advised to update the firmware version to v1.1.9, otherwise future firmware will not be able to install.
- Users may skip updating the remote controller if they have already updated the firmware to v1.1.8, as the latest firmware update does not affect the remote controller.

2015.5.8

Overview :

1. All-in-One Firmware version updated to : v1.1.8

Major Updates :

1. Fixed the issue of failure to update the firmware if the remote controller is turned off.

Notice :

- Users are advised to update the firmware version to v1.1.8, otherwise future firmware will not be able to install.
- Re-link the remote controller to the aircraft if the connection is lost after the firmware update.

2015.5.6

Overview :

1. All-in-One Firmware version updated to : v1.1.6
2. DJI Pilot app iOS version updated to: v1.1.1
3. DJI Pilot app Android version updated to: v1.1.0

Major Updates :

1. Updated to be compatible with the iOS version of the DJI Pilot app.

Notice :

Re-link the remote controller to the aircraft if the connection is lost after the firmware upgrade.